

Material Safety Data Sheet

May be used to comply with
OSHA's Hazard Communication Standard,
29 CFR 1910.1200. Standard must be
consulted for specific requirements.

U.S. Department of Labor

Occupational Safety and Health Administration

(Non-Mandatory Form)

Form Approved

OMB No. 1218-0072



IDENTITY (As Used on Label and List)

Strip, Beading, Sprue, Bite Blocks

Note: Blank spaces are not permitted. If any item is not applicable, or no information is available, the space must be marked to indicate that.

Section I

Manufacturer's Name

KEYSTONE INDUSTRIES

Address (Number, Street, City, State, and ZIP Code)

616 Hollywood Av

Cherry Hill, NJ 08002

Emergency Telephone Number

800-535-5053

Telephone Number for Information

(856) 663-4700

Date Prepared

July 2003

Reviewed August 2006

Signature of Preparer (optional)

Section II — Hazardous Ingredients/Identity Information

Hazardous Components (Specific Chemical Identity; Common Name(s))	OSHA PEL	ACGIH TLV	Other Limits Recommended	% (optional)
---	----------	-----------	--------------------------	--------------

N/A

N/A

N/A

Section III — Physical/Chemical Characteristics

Boiling Point	N/A	Specific Gravity (H ₂ O = 1)	35/36
Vapor Pressure (mm Hg.)	N/A	Melting Point	140-150°F
Vapor Density (AIR = 1)	N/A	Evaporation Rate (Butyl Acetate = 1)	N/A
Solubility in Water	Not Soluble		

Appearance and Odor

Red Green And Pink waxes in various forms

Section IV — Fire and Explosion Hazard Data

Flash Point (Method Used)	Flammable Limits	LEL	UEL
520 Min. open cup			
Extinguishing Media	Foam Dry Chemicals		

Special Fire Fighting Procedures

Cool exposed containers with water spray Recommend the use of self-contained breathing apparatus Best method to extinguish is to smother

Unusual Fire and Explosion Hazards

NONE

Section V — Reactivity Data

Stability	Unstable		Conditions to Avoid	Excessive Heat
	Stable	X		

Incompatibility (Materials to Avoid)

Strong oxidants like chlorine and concentrated O₂

Hazardous Decomposition or Byproducts

None Specified

Hazardous Polymerization	May Occur		Conditions to Avoid	Excessive Heat
	Will Not Occur	X		

Section VI — Health Hazard Data

Route(s) of Entry: Inhalation? N/A Skin? N/A Ingestion? N/A

Health Hazards (Acute and Chronic)

N/A N/A N/A

Carcinogenicity: N/A NTP? N/A IARC Monographs? N/A OSHA Regulated? N/A

Signs and Symptoms of Exposure

From contact with molten wax, skin will show signs of burns

Medical Conditions

Generally Aggravated by Exposure Eczema and dermatitis

Emergency and First Aid Procedures

Flush skin with cool water and seek medical attention

Section VII — Precautions for Safe Handling and Use

Steps to Be Taken in Case Material Is Released or Spilled

Recover free solids and add absorbent to liquid spills

Waste Disposal Method

Dispose of in accordance to local, state and federal regulations

Precautions to Be Taken in Handling and Storing

Keep containers tightly closed and away from heat

Other Precautions

Avoid excessive heat and flames

Section VIII — Control Measures

Respiratory Protection (Specify Type)

None Recommended

Ventilation	Local Exhaust	Recommended	Special	N/A
	Mechanical (General)	Recommended	Other	N/A

Protective Gloves

Oil Proof

Eye Protection

Chemical Goggles

Other Protective Clothing or Equipment

Neoprene Apron Long pants and long sleeve shirt

Work/Hygienic Practices

Good lab housekeeping practices