



KEYSPLINT HARD® CLEAR

Anycubic Photon Mono X 6Ks Printer Instructions



PRINTER SETTINGS	KeySplint Hard® Clear
Shrinkage Compensation	X:100.080%, Y:101.291%, Z:100.00%
Layer Height	0.1
Bottom Layer Count	5
Exposure Time	12.75
Bottom Exposure Time	19
Transition Layer Count	5
Transition Layer Type	Linear
Rest Time Before Lift	0
Rest Time After Lift	10
Rest Time After Retract	2
Bottom Lift Distance	15
Lifting Distance	15
Bottom Lift Speed	200
Lifting Speed	200
Bottom Speed Retract	150
Retract Speed	150